







# NO-CONTACT INFRARED THERMOMETER



15 MEASURE

LCD

ACCURATE


ALARMING



LCD BACKLIGHT LARGE SCREEN DISPLAY  
CLEAR DISPLAY OF MEASUREMENT RESULTS



ACCURATE MEASUREMENT  
ERROR WITHIN THE SET TEMPERATURE RANGE ± 0.2°C



TWO COLOR BACKLIGHT  
HIGH TEMPERATURE WARNING

BACKLIGHT WILL CHANGE FROM WHITE TO RED WHEN THE TARGET TEMPERATURE IS HIGHER THAN THE SET THRESHOLD



NON-CONTACT MEASUREMENT  
IT CAN BE REQUIRED WITHOUT TOUCHING THE SKIN TO REDUCE CROSS INFECTION




## SPECIFICATION



MODEL	KT-1000
TYPE	NON-CONTACT
MEASUREMENT RANGE	0°C-42°C
MEASUREMENT RANGE	32°C-42°C
MEASUREMENT RANGE	32°C-42°C ±0.2°C
MEASUREMENT RANGE	±0.2°C
MEASUREMENT RANGE	37.5°C-42°C
MEASUREMENT RANGE	37.5°C-42°C
MEASUREMENT RANGE	DC 3V (2*AAA BATTERY)
MEASUREMENT RANGE	GREEN AND RED
MEASUREMENT RANGE	15 SECONDS
MEASUREMENT RANGE	32MM-100MM (1.25IN-4IN)
MEASUREMENT RANGE	1750

## SETUP INSTRUCTIONS



## PRODUCT PHOTOGRAPH

